

2nd year 2nd sem 1st mid R10

MMS

1. Which of the following stainless steels cannot be hardened by heat-treatment? :-> Austenitic and ferritic
2. The only heat-treatment that can be applied to ferritic stainless steels is ----- :-> Annealing
3. 18-8 stainless steel consists ----- :-> 18% Cr and 8% Ni www.Examsadda.com
4. In austenitic stainless steels, the total content of Nickel and Chromium will be at least ----- % :-> 23
5. Which of the following stainless steels are non-magnetic? :-> Austenitic
6. The corrosion resistance of stainless steels is high due to the presence of high amount of ----- :-> Cr
7. The corrosion resistance of which of the following stainless steels will be maximum? :-> Austenitic
8. The microstructure of 12% Chromium steels in the annealed condition consists ----- :-> Small carbide particles in a ferrite matrix
9. The microstructure of 18%Cr, 8%Ni steel after annealing consists ----- :-> All austenitic
10. The maximum carbon content in 304L stainless steel is about ----- % :-> 0.03
11. Cemented carbides are manufactured by ----- technique :-> Powder metallurgy
12. The most widely used tungsten base high speed tool steel contain tungsten of about ----- percent :-> 18
13. In high speed tool steels, the carbon content varies between ----- % :-> 0.7 to 1.0
14. The most widely used tungsten-base tool steel is ----- :-> 18-4-1
15. The machinability and general workability of tool steels will ----- with increase in carbon content. :-> Decrease
16. In 18-4-1 high speed tool steels, the amount of Vanadium is ----- % :-> 1
17. In 18-4-1 high speed tool steels, the amount of chromium is ----- % :-> 4
18. The only alloying element which decreases hardenability is ----- :-> Co
19. The carbon content in shock-resisting tool steels varies between ----- % :-> 0.45 to 0.65
20. The principal alloying elements in mold steels are ----- :-> Cr and Ni
21. Fine-grained Manganese steels are often used for ----- :-> Gears, axles and spline shafts
22. Which of the following element in steels has an outstanding ability to combine with sulfur? :-> Mn
23. Which of the following steels contain Manganese of about 12% :-> Hadfield Manganese steels
24. Hadfield manganese steel usually contain manganese of about ----- percent :-> 12
25. Maraging steels contain carbon of about ----- % :-> 0.03
26. Which of the following element in steels will reduce the harmful effect of hot-shortness? :-> Mn
27. The function of manganese in manganese steels is ----- :-> Acts as deoxidizer and reduces tendency towards hot shortness
28. Nickel content in Nickel maraging steels will be about ----- % :-> 20
29. Due to the use of low aging temperatures, distortion will be less in ----- steels :-> Maraging
30. Which of the following is a function of Vanadium in steels? :-> Acts as a powerful deoxidizer and inhibits grain growth
31. Which of the following is a function of 'P' in steels? :-> Strengthens low carbon steels
32. Which of the following is a function of silicon in steels? :-> Acts as a deoxidizer
33. The addition of alloying elements to steels will increase ----- :-> Strength, wear resistance and corrosion resistance
34. Which of the following alloying elements will reduce the austenitic region in Fe-Fe₃C diagram? :-> Mo
35. Which of the following is an austenite stabilizer? :-> Ni
36. Which of the following alloying elements will reduce the eutectoid temperature? :-> Ni
37. The presence of which of the following alloying element will raise the critical temperature in the Fe-Fe₃C diagram on heating? :-> Mo www.Examsadda.com
38. The presence of which of the following alloying element will lower the critical temperature line in the Fe-Fe₃C diagram on heating? :-> Ni
39. Steels containing ----- are less susceptible to temper brittleness than other alloy steels. :-> Mo
40. Which of the following steels are more brittle? :-> High carbon steels
41. Which of the following steels cannot be hardened by heat-treatment? :-> Low carbon steels
42. The amount of carbon present in high carbon steels is ----- % :-> >0.6

43. The amount of carbon present in medium carbon steels is ----- % :->0.3 to 0.6
44. The amount of carbon present in low carbon steels is ----- %:->0 to 0.3
45. When 0.2%C steel is heated just above the A₁ line, pearlite will transform to -----:->Austenite
46. The microstructure of 0.2%C steel above A₃ line consists -----:->Fine-grained austenite
47. Proper annealing temperature for hypo eutectoid steels is approximately -----:->50F above the A₃ line
line *www.Examsadda.com*
48. The recommended austenizing temperature for hypo eutectoid steels is about ----- :->50F above the upper critical temperature line
49. The effect of addition of small amount of chromium to the cast irons is ----- :->Increases strength and decreases machinability
50. Small addition of chromium to cast irons will decrease ----- :->Machinability
51. Ferritic nodular iron consists ----- in a ferritic matrix :->Graphite spheroids
52. The total carbon content of nodular cast iron is same as in ----- cast iron:->Grey
53. Spheroidal graphite cast iron is also known as ----- :->Nodular cast iron
54. The addition of Vanadium to the cast irons between 0.1 to 0.25% will -----:->Increase tensile strength and hardness
55. Which of the following is a strong carbide forming element? :->Cr
56. Which of the following element will be added to the ladle just before casting to form nodules? :->Mg
57. The addition of 14 to 38% Nickel to grey irons results in ----- :->High heat resistance and low expansivity
58. The addition of about 4% Nickel in combination with 1.5% Chromium will improve ----- of white cast iron :->Abrasion resistance
59. Most grey cast irons contain carbon between ----- % :->2.5 to 4
60. Most grey cast irons are ----- :->Hypo eutectic alloys
61. Which of the following is an industrial application of pearlitic malleable iron?:->Axles, camshafts and crankshafts
62. A fully ferritic malleable iron can be converted to pearlitic malleable iron by which of the following treatments? :->Reheating above the lower critical temperature followed by rapid cooling
63. The purpose of malleabilization is to convert all the combined carbon in white cast iron into -----:->temper carbon and ferrite
64. Which of the following is a strong graphitizer? :->Si
65. The graphitization process can be aided by -----:->Adding silicon
66. In the malleabilization treatment, white cast iron will be heated between -----F :->1650 to 1750
67. Completely white cast irons are limited in engineering applications because of their -----:->High brittleness
68. Which of the following is not an application of white cast iron? :->Springs
69. Hyper eutectic cast irons contain carbon between ----- % :->4.3 to 6.67
70. Hypo eutectic cast irons contain carbon between ----- % :->2.0 to 4.3
71. In ----- cast irons all the carbon will be in the combined form. :->White
72. Cast irons contain carbon between -----% :->2.0 to 6.67
73. Which of the following is used as a starting material for malleable cast iron?:->White cast iron
74. The micro structure of white cast iron consists of ----- at 250X magnification:->Pearlite and cementite
75. The tensile strength of white cast iron is about ----- Psi :->20,000 to 70,000
76. The density of white cast iron is about ----- Kg/m³ :->7.7 X 10³
77. Iron carbide, a common constituent of steels is ----- :->An intermetallic compound
78. According to Hume Rothery, for the formation of solid solution, the difference in atomic radii should be less than about -----%:->15
79. Complete solid solubility of two elements will be attained when the elements have ----- :->Same type of crystal lattice structure *www.Examsadda.com*
80. ----- are formed when atoms of small atomic radii fit into the spaces of the lattice structure of the larger solvent atoms.:->Interstitial solid solution
81. A solution in which, the atoms of the solute substitute for atoms of the solvent in the lattice structure of the solvent is known as -----:->Substitutional solid solution
82. The minor part of the solution is known as -----:->Solute

83. In Hume Rothery rules for extensive solid solubility, the atomic diameter of the solute and the solvent atoms should not differ by more than ----- %:->15
84. According to Hume Rothery, which of the following factors favor the formation of solid solution? :-
>Elements with size difference less than 15%
85. The maximum solubility of carbon in α -iron is ----- percent at 1333F:->0.025
86. For ASTM grain size number $n=3$, the number of grains per square inch at 100X magnification are -----:->4
www.Examsadda.com
87. For ASTM grain size number $n=2$, the number of grains per square inch at 100X magnification are -----:->2
88. The number of grains per square inch at 100X magnification is given by -----:-> $N = 2^{n-1}$
89. Which of the following method is used for the measurement of grain size? :->Comparison, intercept and planimetric methods
90. The number of grains per square inch at 100X magnification is 256. The ASTM grain size number is -----:->9
91. The number of grains per square inch at 100X magnification is 16. The ASTM grain size number is -----:->5
92. The length of the line in millimeters divided by the average number of grains intersected by it gives-----:->Grain diameter
93. For measuring the size of non-equiaxed grains, which of the following methods is preferred?:->Heyn's intercept method
94. If the equivalent number of whole grains at a magnification of 200X was 62, and Jafferies multiplier is 8.0, the number of grains per square millimeter is equal to -----:->496
95. If the equivalent number of whole grains is 75, at a magnification of 100X and Jafferies multiplier is 2, the number of grains per square millimeter is equal to -----:->150
96. With increasing cold work :->Tensile strength increases and electrical conductivity decreases
97. As compared to the nucleation rate maximum, the growth rate maximum will be at -----:->A higher temperature
98. The recrystallization temperature decreases with -----:->decreasing cold working temperature
99. The process of nucleation and growth of new strain free crystals, which replace all the deformed crystals of the worked materials is called -----:->Recrystallization
100. Grain growth occur in the temperature range----- :->0.4 - 1.0T_m
101. Which of the treatment results in fine grain size? :->Increasing nucleation rate
102. Which of the following method is used for the measurement of grain size? :->Comparison, intercept and planimetric methods
103. The free energy decrease during recrystallization comes mainly from ----- :->Lower energy of the new crystal structure
104. The recrystallization rate increases with: :->Decreasing initial grain size
105. If the interfacial energy increases by 10%, the homogeneous nucleation barrier for a spherical particle increases by -----% :->133
106. The heat of fusion of metals will be in the range of ----- KJ/mole:->10-15
107. The crystal structure of Aluminum is ----- :->FCC
108. The crystal structure of Nickel is -----:->FCC
109. The crystal structure of gold is ----- :->FCC
110. The crystal structure of silver is -----:->FCC *www.Examsadda.com*
111. The main technique employed for determining the crystal structure is -----:->X-ray diffraction
112. Hydrogen bonds are stronger than ----- :->Vander waals bonds
113. The crystal structure of which of the following metal is BCC? :->Molybdenum
114. The crystal structure of which of the following metal is HCP? :->Cadmium
115. If the Fe-Fe bond length is 2.48 \AA , the radius of the iron atom is ----- \AA :->1.24
116. Thermal expansion of materials arises from -----:->Asymmetry of potential energy curve
117. The fraction of eutectoid ferrite in 0.2%C steel is ----- :->0.22
118. The fraction of proeutectoid ferrite in 0.2%C steel is ----- :->0.75
119. The fraction of proeutectoid cementite in 1.0%C steel is ----- :->0.034
120. The fraction of proeutectoid cementite in 1.4%C steel is ----- :->0.10

121. The fraction of pearlite in a slowly cooled 0.6% C steel is ----- :>0.75
122. The fraction of proeutectoid ferrite in a slowly cooled 0.6%C steel is -----:>0.25
123. If the fraction of liquid with 57%B, which is in equilibrium with solid of 82%B is 0.7, the overall composition is -----:>64.5%B
124. If alpha of 82% B and liquid of 57% B are in equilibrium in an alloy of 73%B, the fraction of liquid is ----- :>0.36 *www.examsadda.com*
125. In a binary sustem of A and B, if a liquid of 35%A (65%B) is coexisting with a solid of 75%A (25%B), for an overall composition of 40%A, the fraction of the liquid is given by -----:>0.875
126. In the eutectic phase diagram of Ag-Cu system, the solubility limit at 500°C of copper is 3% in the Ag rich phase and of Ag is 2% in the Cu rich phase. In sterling silver (92.5% Ag - 7.5 % Cu), the percent of copper in the Ag rich phase at 500°C is -----:>3
127. The degrees of freedom of a system of two components when the number of phases are four is ----->0
128. The phase rule for the condensed phases is given by ----- :>F = C-P+1
129. The degrees of freedom of a system of two components when the number of phases is two is ----->2
130. The degrees of freedom when ice, water and water vapor coexist in equilibrium is -----:>0
131. Physically distinct, chemically homogeneous and mechanically separable region of the system is known as -----:>Phase
132. Gibbs phase rule is given by::>F = C-P+2
133. The maximum number of phases in equilibrium in a system corresponds to F = -----:>0
134. In a single component system, the maximum number of phases that can co-exist in equilibrium is ----->3
135. At atmospheric pressure, a material of unknown composition shows four phases in equilibrium at 987K. The minimum number of components in the system is -----:>3
136. The degrees of freedom, when FCC and BCC iron coexist in equilibrium are -----:>1
137. An isothermal reversible reaction in which a solid phase reacts with a second solid phase to produce a third solid phase on cooling is known as ----- reaction :>Peritectoid
138. Solid 1 + Solid 2 = Solid 3. Represents ----- reaction :>Peritectoid
139. Alloys to the right of the eutectoid composition are known as ----- alloys:>hypereutectoid
140. Alloys to the left of the eutectoid composition are known as ----- alloys :>hypoeutectoid
141. Which of the following represents eutectoid reaction? :>Solid 1 = Solid 2 + Solid 3
142. Which of the following is a solid state reaction? :>peritectoid
143. Solid 1 = Solid 2 + Solid 3. Represents ----- reaction :>eutectoid
144. Which of the following is a solid state reaction? :> Eutectoid
145. Which of the following is not a solid state reaction?:>Monotectic
146. Which of the following represents peritectoid reaction?:>Solid 1 + Solid 2 = Solid 3
147. Which of the following is true? :>Allotropy is a reversible phenomenon
148. The number of allotropic forms exhibited by iron is ----- :>3
149. The crystal structure of γ -iron is -----:>fcc
150. The crystal structure of δ iron is -----:>bcc
151. Which of the following is true? :>Allotropy is a reversible phenomenon
152. The reversible phenomenon by which certain metals exist in more than one crystal structure is known as ----- :>Allotropy *www.examsadda.com*
153. For pure iron the allotropic change from δ -iron to α -iron occurs at -----°C :>910
154. For pure iron, the allotropic change from δ -iron to γ -iron occurs at -----°C :>1400
155. The γ -solid solution is formed by ----- reaction in Fe-Ni equilibrium diagram :>Peritectic
156. Which of the following metals does not exhibit allotropic property? :>Nickel
157. Which of the following metals exhibit allotropic property? :>Iron, tin and manganese
158. In Fe-Fe₃C equilibrium diagram peritectic reaction occurs at -----°C :>1493
159. Which of the following shows peritectic reaction?:>Liquid + Solid = New Solid
160. Which of the following is true? :>In a peritectic system, a liquid and a solid react isothermally to form a new solid on cooling

161. In ----- reaction, a liquid and a solid react isothermally to form a new solid on cooling.:-
>Peritectic
162. When one phase changes into another phase isothermally and without any change in chemical composition, it is said to be ----- change:->**congruent phase change**
163. The phase diagram of which of the following alloy system shows peritectic reaction? :->**Ag - Pt**
164. Liquid + Solid = New solid . Represents ----- reaction :->**Peritectic**
165. Magnesium and Tin form an intermediate phase with formula ----- :->**Mg₂Sn**
166. The phase diagram of Ag - Pt alloy system consists ----- reaction :->**Peritectic**
167. Silver-Platinum alloy system shows the formation of a terminal solid solution by ----- reaction
 :->**peritectic**
168. In copper - nickel alloy : :->**there is no eutectic point**
169. Alloys to the right of the eutectic composition are known as ----- alloys:->**hyper eutectic**
170. Alloys to the left of the eutectic composition are known as ----- alloys :-> **hypo eutectic**
171. Solidification of eutectic alloy occurs at ----- temperature :->**constant**
172. The change of a liquid of a particular composition into two solids at constant temperature is known as ----- reaction:->**eutectic**
173. As the eutectic composition is approached from the plastic-phase side, the strength of the alloy will ----- :->**increase**
174. Liquid = solid A + solid B represents ----- reaction:->**eutectic**
175. Two metals completely soluble in the liquid state and completely insoluble in the solid state yield ----- system :->**Eutectic**
176. The eutectic temperature of lead-tin binary alloy is ----- °C :->**183**
177. Beyond the eutectic point, the strength of the alloy will decrease, due to ----- :->**increase in size and amount of proeutectic brittle phase**
178. Which of the following metals are completely soluble in liquid and solid states? :->**copper, nickel**
179. Coring occurs due to ----- :->**non-equilibrium cooling**
180. In the phase diagram of two metals completely soluble in liquid and solid states, the area above the liquidus line consists of -----:->**homogeneous liquid solution**
181. In equilibrium diagrams the line obtained by connecting the points showing the end of solidification is called ----- :->**Solidus line**
182. In equilibrium diagrams the line obtained by connecting the points showing the beginning of solidification is called ----- :-> **Liquidus line**
183. The cooling curve for pure metals shows a horizontal line because ----- :-> **the beginning and end of solidification takes place at constant temperature**
184. The rate of diffusion of one metal in another is specified by the diffusion coefficient, and its value doubles for every ----- °C rise in temperature:->**20**
185. Two metals completely soluble in liquid and solid states yield ----- alloy system:->**Isomorphous**
186. The relative amounts of two phases in equilibrium at any specified temperature in a two phase region can be determined by ----- rule:->**Lever**
187. Cored structures are most common in ----- metals:->**as-cast**
188. Binary phase diagrams are plots between -----:->**temperature and composition**
189. Soldering lead is a ----- component system :->**two**
190. Thermodynamically, the system is in equilibrium means, the free energy of the system will be -----
 :->**minimum**
191. In order to specify completely the state of a system in equilibrium, the number of independent variables necessary to specify are ----- :->**three**
192. Phase diagrams are plotted with ----- as the ordinate and ----- as the abscissa :-
>Temperature, alloy composition in weight percentage
193. X-ray diffraction method indicates the appearance of a new phase by -----:->**either change in lattice dimension or the appearance of a new crystal structure**
194. In order to specify completely the state of a system in equilibrium, the independent variables necessary to specify are -----:->**temperature, pressure and composition**
195. Which of the following experimental methods will be used for the construction of equilibrium diagrams?:->**X-ray diffraction**

196. Zone refining will be more efficient if the ratio of impurity in the solid to that in the liquid is -----
 :->**0.01**